

FIG. 1A




FIG. 1B

10206 M-10970 US  
(2719)




FIG. 1C




FIG. 1D

10206 M-10970US  
(30719)




FIG. 2A

10206 M-10970 VS  
(40619)




FIG. 2B

16204 M-10970 VS  
(50/19)





FIG. 2C

10206 M-10970 VS  
(60719)




TRANSCIVER  
BLOCK DIAGRAM

FIG. 2D




10206 M-1097015  
(7819)

FIG. 2E



TRANSMITTER  
BLOCK DIAGRAM

FIG. 2E





10206 M-10970 US  
(9819)




FIG. 3D

10206 M-1097005  
(10/19)




FIG. 3E

10206 M-10990 US  
(11 of 19)




Figure 4




FIG. 5A




FIG. 5B




FIG. 5C




FIG. 5D




FIG. 5E









FIG. 5F



10206 M-10970 US  
(1953/9)

relative  
radiative  
capture



off-axis  
angle of incidence

FIG. 5I